

Latex Printer Settings

Profiles Available:



All profiles are available for download at: www.fishertextiles.com/profiles.php

L26500, L28500 Printers:

Rip: Caldera
Load as: Fabric
Print Mode: 10 passes unidir
InkLimit: Normal
Drying temperature: 55°C
Curing temperature: 100°C
Airflow: 30%
OMAS: Enable
Cutter: Disable
Tension: 15N/m
Vaccum: 20mmH20
WUDTO: 5°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 1kW

Rip: ColorGate
Load as: Fabric
Print Mode: 12 passes bidi
InkLimit: High
Drying temperature: 55°C
Curing temperature: 100°C
Airflow: 45% **OMAS:** Enable
Cutter: Disable
Tension: 15N/m
Vaccum: 20mmH20
WUDTO: 5°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 0,7kW

Rip: Ergosoft
Load as: Banner
Print Mode: 12 passes bidi
InkLimit: High
Drying temperature: 55°C
Curing temperature: 100°C
Airflow: 45%
OMAS: Enable
Cutter: Disable
Tension: 15N/m
Vaccum: 20mmH20
WUDTO: 5°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 0,7kW

Rip: Onyx10
Load as: Banner
Print Mode: 12 passes bidi
InkLimit: Normal
Drying temperature: 50°C
Curing temperature: 100°C
Airflow: 45%
OMAS: Enable
Cutter: Disable
Tension: 15N/m
Vaccum: 10mmH20
WUDTO: 5°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 0,7kW

Rip: Sai
Load as: Fabric
Print Mode: 10 passes unidir
InkLimit: High
Drying temperature: 55°C
Curing temperature: 100°C
Airflow: 45%
OMAS: Enable
Cutter: Disable
Tension: 15N/m
Vaccum: 20mmH20
WUDTO: 5°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 1kW

Rip: Wasatch
Load as: Banner
Print Mode: 12 passes bidi
InkLimit: High
Drying temperature: 55°C
Curing temperature: 100°C
Airflow: 45%
OMAS: Enable
Cutter: Enable
Tension: 15N/m
Vaccum: 20mmH20
WUDTO: 0°C
WUCTO: 0°C
CDDTO: 0°C
CDCTO: 0°C
Pmin: 0,8kW

